

DuraMetl Metallic Colors Instructions

DuraMetl creates a sophisticated metallic look to firearms and accessories while offering the same durability and corrosion free properties as the original DuraCoat finishes. DuraMetl can be applied to all types of metal, plastic, and wood including optics and accessories.

- 1) Disassemble firearm as far as you feel comfortable.
- 2) Degrease parts with LCW TruStrip Cleaner/Degreaser.
- 3) If coating over an existing paint, spray on, or bake on finish, or if you do not know what the existing finish is, we recommend roughing up the surface by sanding or sandblasting.
- 4) Apply a base coat of any DuraCoat color. The color choice will affect the final look of the DuraMetl.
- 5) Allow the DuraCoat base coat to dry for at least one hour.
- 6) Mix 8 parts DuraMetl with 1 part hardener.
- 7) Reduce with DuraCoat Reducer only if necessary up to 20% by volume
- 8) Apply DuraMetl with an airbrush or spray gun. Allow to dry at least 20 minutes.
- 9) Top coat with DuraLaser Clear. Allow to dry.
- 10) Do not allow more than 7 days to pass between the base coat and top coat.

Parts coated with DuraMetl can be reassembled and used after 24 hours. It will take 3-4 weeks for a full cure to be reached. Do not apply harsh cleaners, use in holster, or subject to harsh use during the cure time.